

**INSPECTION SHEET 検品書**  
**CRAWLER CRANE クローラクレーン**

INSPECTION DATE	2025/7/29	MAKE	MAEDA	MODEL	CC-505
SERIAL No.	PLATE :	C00203	STAMP	C00203	
HR METER	3927	HR	SHOE	450ROAD LINER	YEAR YR

<b>ENGINE : MODEL</b> 4D95LE-1 <b>S/N</b> 206650	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn 白煙あり WHITE FUMES
<b>OPERATION PUMP</b>	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
<b>COOLING SYSTEM</b>	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
<b>OPERATING SYSTEM</b>	
Computer	<input checked="" type="radio"/> OK · NG
Swing	<input checked="" type="radio"/> FAIR · Attn ガタあり SWING: LOOSE
Travel	<input checked="" type="radio"/> FAIR · Attn
<b>BOOM</b>	
MAIN BOOM	
BOOM TOTAL	
TOP SHEAVE	YES · <input checked="" type="radio"/> NO
JIB	
TOWER	

<b>INTERIOR</b> See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · <input checked="" type="radio"/> DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn 破れあり CUTS
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	
<b>COMMENT</b>	
WEIGHT	-
HOOK	4.9t
LIFTER	YES · <input checked="" type="radio"/> NO
<b>COMMENT</b>	
CAB	
起伏シリンダー油漏れあり DERRICKING CYLINDER: OIL LEAKING	
メーター内曇りあり、見づらい	
INSIDE OF INDICATOR COVER: CLOUDY (HARD TO READ)	
CABドア外側持ち手破損あり OUTSIDE DOOR KNOB: BROKEN	
5段ブーム 5-SECTION BOOM	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。