

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/29	MAKE	KOMATSU	MODEL	PC200-8N1
SERIAL	315873		STAMP	KMTPC197H02315873	
HR METER	4541	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

<table style="width: 100%;"> <tr> <td style="width: 50%;">ENGINE : MODEL</td> <td style="width: 50%;">S/N</td> </tr> <tr> <td>Oil leakage</td> <td>FAIR · Attn</td> </tr> <tr> <td>Blow-By</td> <td>FAIR · Attn A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td>FAIR · Attn</td> </tr> <tr> <td>Oil</td> <td>FAIR · Attn</td> </tr> <tr> <td>Exhaust Color</td> <td>FAIR · Attn</td> </tr> <tr> <td>US EPA</td> <td>YES · NO</td> </tr> <tr> <td colspan="2">MAIN PUMP</td> </tr> <tr> <td>Sound</td> <td>FAIR · Attn</td> </tr> <tr> <td>Oil leakage</td> <td>FAIR · Attn</td> </tr> <tr> <td>Power</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td>FAIR · Attn</td> </tr> <tr> <td>Oil Cooler</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">OPERATING SYSTEM</td> </tr> <tr> <td>Swing</td> <td>FAIR · Attn</td> </tr> <tr> <td>Travel</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND.</td> <td>CLEAN · FAIR · DIRTY</td> </tr> <tr> <td>Operator's Seat</td> <td>FAIR · Attn 切れあり CUTS</td> </tr> <tr> <td>Glasses</td> <td>FAIR · Attn</td> </tr> <tr> <td>AirCon</td> <td>A/C · H/C · H only · C only · None</td> </tr> <tr> <td colspan="2">BOOM / ARM / BKT</td> </tr> <tr> <td>Boom</td> <td>FAIR · Attn</td> </tr> <tr> <td>Boom Cylinder</td> <td>FAIR · Attn</td> </tr> <tr> <td>Arm</td> <td>FAIR · Attn</td> </tr> <tr> <td>Arm Cylinder</td> <td>FAIR · Attn</td> </tr> <tr> <td>BKT</td> <td>FAIR · Attn</td> </tr> <tr> <td>BKT Cylinder</td> <td>FAIR · Attn</td> </tr> </table>	ENGINE : MODEL	S/N	Oil leakage	FAIR · Attn	Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE	Sound	FAIR · Attn	Oil	FAIR · Attn	Exhaust Color	FAIR · Attn	US EPA	YES · NO	MAIN PUMP		Sound	FAIR · Attn	Oil leakage	FAIR · Attn	Power	FAIR · Attn	COOLING SYSTEM		Radiator	FAIR · Attn	Oil Cooler	FAIR · Attn	OPERATING SYSTEM		Swing	FAIR · Attn	Travel	FAIR · Attn	INTERIOR See Photos. 写真参照		INTERIOR COND.	CLEAN · FAIR · DIRTY	Operator's Seat	FAIR · Attn 切れあり CUTS	Glasses	FAIR · Attn	AirCon	A/C · H/C · H only · C only · None	BOOM / ARM / BKT		Boom	FAIR · Attn	Boom Cylinder	FAIR · Attn	Arm	FAIR · Attn	Arm Cylinder	FAIR · Attn	BKT	FAIR · Attn	BKT Cylinder	FAIR · Attn	<table style="width: 100%;"> <tr> <td colspan="2">UNDERCARRIAGE : See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td>3</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr> <td>BKT</td> <td>STD / SLOPE / NARROW / SKELETON / OTHER ()</td> </tr> <tr> <td>Lever</td> <td>LONG · WRIST</td> </tr> <tr> <td>Multi</td> <td>MULTI · 2 · NO</td> </tr> <tr> <td>ARM-CRANE</td> <td>YES · NO</td> </tr> <tr> <td>BLADE</td> <td>YES · NO</td> </tr> <tr> <td>OFFSET</td> <td>YES · NO</td> </tr> <tr> <td>OFFSET Cylinder</td> <td>FAIR · Attn</td> </tr> <tr> <td>Piping</td> <td>YES · NO Breaker only · Multi</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> </tr> <tr> <td colspan="2">3</td> </tr> </table>	UNDERCARRIAGE : See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	COMMENT														BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()	Lever	LONG · WRIST	Multi	MULTI · 2 · NO	ARM-CRANE	YES · NO	BLADE	YES · NO	OFFSET	YES · NO	OFFSET Cylinder	FAIR · Attn	Piping	YES · NO Breaker only · Multi	COMMENT																				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
ENGINE : MODEL	S/N																																																																																																																				
Oil leakage	FAIR · Attn																																																																																																																				
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE																																																																																																																				
Sound	FAIR · Attn																																																																																																																				
Oil	FAIR · Attn																																																																																																																				
Exhaust Color	FAIR · Attn																																																																																																																				
US EPA	YES · NO																																																																																																																				
MAIN PUMP																																																																																																																					
Sound	FAIR · Attn																																																																																																																				
Oil leakage	FAIR · Attn																																																																																																																				
Power	FAIR · Attn																																																																																																																				
COOLING SYSTEM																																																																																																																					
Radiator	FAIR · Attn																																																																																																																				
Oil Cooler	FAIR · Attn																																																																																																																				
OPERATING SYSTEM																																																																																																																					
Swing	FAIR · Attn																																																																																																																				
Travel	FAIR · Attn																																																																																																																				
INTERIOR See Photos. 写真参照																																																																																																																					
INTERIOR COND.	CLEAN · FAIR · DIRTY																																																																																																																				
Operator's Seat	FAIR · Attn 切れあり CUTS																																																																																																																				
Glasses	FAIR · Attn																																																																																																																				
AirCon	A/C · H/C · H only · C only · None																																																																																																																				
BOOM / ARM / BKT																																																																																																																					
Boom	FAIR · Attn																																																																																																																				
Boom Cylinder	FAIR · Attn																																																																																																																				
Arm	FAIR · Attn																																																																																																																				
Arm Cylinder	FAIR · Attn																																																																																																																				
BKT	FAIR · Attn																																																																																																																				
BKT Cylinder	FAIR · Attn																																																																																																																				
UNDERCARRIAGE : See Photos. 写真参照																																																																																																																					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																																																				
COMMENT																																																																																																																					
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()																																																																																																																				
Lever	LONG · WRIST																																																																																																																				
Multi	MULTI · 2 · NO																																																																																																																				
ARM-CRANE	YES · NO																																																																																																																				
BLADE	YES · NO																																																																																																																				
OFFSET	YES · NO																																																																																																																				
OFFSET Cylinder	FAIR · Attn																																																																																																																				
Piping	YES · NO Breaker only · Multi																																																																																																																				
COMMENT																																																																																																																					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																																																																					
3																																																																																																																					

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。