

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

|                 |                 |      |                    |          |           |
|-----------------|-----------------|------|--------------------|----------|-----------|
| INSPECTION DATE | 2025/8/21       | MAKE | KATO               | MODEL    | KR-25H-V6 |
| SERIAL No.      | PLATE : 5411827 |      | STAMP : KR258-1827 |          |           |
| HR METER        | ERROR HR        |      | Odometer           | ERROR km |           |
| TIRE SIZE       | 385/95R25       |      | YEAR               | YR       |           |

| ENGINE : MODEL                        |                                               | S/N                        |
|---------------------------------------|-----------------------------------------------|----------------------------|
| Oil leakage                           | <div>FAIR</div> · Attn                        |                            |
| Blow-By                               | <div>FAIR</div> · Attn                        | A LITTLE · MIDDLE · SEVERE |
| Sound                                 | <div>FAIR</div> · Attn                        |                            |
| Oil                                   | <div>FAIR</div> · Attn                        |                            |
| Exhaust Color                         | <div>FAIR</div> · Attn                        |                            |
| <b>OPERATION PUMP</b>                 |                                               |                            |
| Sound                                 | <div>FAIR</div> · Attn                        |                            |
| Oil leakage                           | <div>FAIR</div> · Attn                        |                            |
| Power                                 | <div>FAIR</div> · Attn                        |                            |
| <b>COOLING SYSTEM</b>                 |                                               |                            |
| Radiator                              | <div>FAIR</div> · Attn                        |                            |
| Oil Cooler                            | <div>FAIR</div> · Attn                        |                            |
| <b>OPERATING SYSTEM</b>               |                                               |                            |
| Computer                              | <div>OK</div> · NG                            |                            |
| Swing                                 | <div>FAIR</div> · Attn                        |                            |
| Travel                                | <div>FAIR</div> · Attn                        |                            |
| <b>TRANSMISSION</b>                   |                                               |                            |
| Transmission                          | <div>FAIR</div> · Attn                        |                            |
| No. OF GEARS                          | 4 GEAR                                        |                            |
| 4WD                                   | <div>4WD</div> · 6WD                          |                            |
| <b>INTERIOR      See Photos. 写真参照</b> |                                               |                            |
| INTERIOR COND.                        | CLEAN · <div>FAIR</div> · DIRTY               |                            |
| Operator's Seat                       | <div>FAIR</div> · Attn                        |                            |
| Glasses                               | <div>FAIR</div> · Attn                        |                            |
| AirCon                                | <div>A/C</div> · H/C · H only · C only · None |                            |
| <b>COMMENT</b>                        |                                               |                            |
|                                       |                                               |                            |
|                                       |                                               |                            |
|                                       |                                               |                            |

|                                                                      |                         |         |                   |       |   |
|----------------------------------------------------------------------|-------------------------|---------|-------------------|-------|---|
| BOOM                                                                 |                         |         |                   |       |   |
| No. of Section                                                       | 4                       |         | SECTIONS          |       |   |
| CRACK/ENFORCEMENT                                                    | (FAIR)                  | ▪ Attn  |                   |       |   |
| DERRICKING CYL.                                                      | (FAIR)                  | ▪ Attn  |                   |       |   |
| EXTENSION CYL.                                                       | (FAIR)                  | ▪ Attn  |                   |       |   |
| JIB                                                                  | (YES)                   | ▪ NO    | 腐食大 MUCH CORRODED |       |   |
| JIB TYPE                                                             | STD                     | ▪ (PWR) |                   |       |   |
| MAIN & SUB WIRE                                                      | (YES)                   | ▪ NO    |                   |       |   |
| FREE FALL                                                            | (YES)                   | ▪ NO    |                   |       |   |
| HOOK                                                                 | 26t, BALL               |         |                   |       |   |
| UNDERCARRIAGE : See Photos. 写真参照                                     |                         |         |                   |       |   |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         |                         |         |                   |       | 1 |
| TIRE WEAR                                                            | FAIR (WORN) UNEVEN WEAR |         |                   |       |   |
| COMMENT                                                              |                         |         |                   |       |   |
|                                                                      |                         |         |                   |       |   |
|                                                                      |                         |         |                   |       |   |
| OUTRIGGERS                                                           |                         |         |                   |       |   |
| OUTRIGGERS                                                           | (X)                     | ▪ H     |                   |       |   |
| OUTRIGGERS COND.                                                     | (FAIR)                  | ▪ Attn  |                   |       |   |
| Oil leakage (JACK CYL.)                                              | FRONT                   | L ▪ R   | REAR              | L ▪ R |   |
| Oil leakage (SLIDE CYL.)                                             | FRONT                   | L ▪ R   | REAR              | L ▪ R |   |
| COMMENT                                                              |                         |         |                   |       |   |
|                                                                      |                         |         |                   |       |   |
|                                                                      |                         |         |                   |       |   |
|                                                                      |                         |         |                   |       |   |
|                                                                      |                         |         |                   |       |   |
|                                                                      |                         |         |                   |       |   |
|                                                                      |                         |         |                   |       |   |
|                                                                      |                         |         |                   |       |   |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |                         |         |                   |       | 1 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。