

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                          |      |     |       |                   |
|-----------------|------------------------------------------|------|-----|-------|-------------------|
| INSPECTION DATE | 2025/10/27                               | MAKE | CAT | MODEL | 320ERR-2          |
| SERIAL          | CAT0320EJLHN00374                        |      |     | STAMP | CAT0320EJLHN00374 |
| HR METER        | 8629 / 8645                              |      | HR  | YEAR  | YR                |
| CAB/CNP         | (ROPS CAB) / CAB / ROPS CNP / CNP / NONE |      |     | SHOE  | 600G              |

|                           |       |      |                            |          |
|---------------------------|-------|------|----------------------------|----------|
| ENGINE : MODEL            |       | C6.6 | S/N                        | C8N20384 |
| Oil leakage               | FAIR  | Attn |                            |          |
| Blow-By                   | FAIR  | Attn | A LITTLE · MIDDLE · SEVERE |          |
| Sound                     | FAIR  | Attn |                            |          |
| Oil                       | FAIR  | Attn |                            |          |
| Exhaust Color             | FAIR  | Attn |                            |          |
| US EPA                    | YES   | NO   |                            |          |
| MAIN PUMP                 |       |      |                            |          |
| Sound                     | FAIR  | Attn |                            |          |
| Oil leakage               | FAIR  | Attn |                            |          |
| Power                     | FAIR  | Attn |                            |          |
| COOLING SYSTEM            |       |      |                            |          |
| Radiator                  | FAIR  | Attn |                            |          |
| Oil Cooler                | FAIR  | Attn |                            |          |
| OPERATING SYSTEM          |       |      |                            |          |
| Swing                     | FAIR  | Attn |                            |          |
| Travel                    | FAIR  | Attn |                            |          |
| INTERIOR See Photos. 写真参照 |       |      |                            |          |
| INTERIOR COND.            | CLEAN | FAIR | DIRTY                      |          |
| Operator's Seat           | FAIR  | Attn | 破れあり CUTS                  |          |
| Glasses                   | FAIR  | Attn | *1                         |          |
| AirCon                    | A/C   | H/C  | H only                     | C only   |
| None                      |       |      |                            |          |
| BOOM / ARM / BKT          |       |      |                            |          |
| Boom                      | FAIR  | Attn |                            |          |
| Boom Cylinder             | FAIR  | Attn |                            |          |
| Arm                       | FAIR  | Attn |                            |          |
| Arm Cylinder              | FAIR  | Attn |                            |          |
| ATTACHMENT                | FAIR  | Attn | ガタあり LOOSE                 |          |
| BKT Cylinder              | FAIR  | Attn |                            |          |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。