

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2025/7/23	CATEGORY	自走式破砕機 MOBILE CRUSHER		
MAKE	KOMATSU		MODEL	BR380JG-1E0	
SERIAL	2099		STAMP	NOT FOUND	
HR METER	UNKNOWN	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	TIRE

ENGINE	MODEL	S/N
Oil leakage	FAIR • Attn 油汚れ大 MUCH OIL STAINS	Oil FAIR • Attn
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE	Exhaust Color FAIR • Attn
Sound	FAIR • Attn	EPA YES • NO

CONDITION	FAIR • Attn	
磁選機モーター油漏れのため磁選機ホースメクラあり(動作不可) MAGNETIC SEPARATOR: OIL LEAKING, HOSES: COVERED WITH CAPS (UNABLE TO WORK) クラッシャーシリンダーにじみあり CRUSHER CYLINDER: OIL OOZING		

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR	FAIR • WORN • UNEVEN WEAR
COMMENT			
ポンプ周り油漏れあり AROUND PUMP: OIL LEAKING			
モニター見えない、確認不可 MONITOR: UNREADABLE, NOT CHECKED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。