

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/7/14	MAKE	KOMATSU	MODEL	D21A-8E0	
SERIAL	90952			STAMP	KMT0D106AFA090952	
HR METER	773	HR	SHOE	300G	YEAR	YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE :	MODEL	4D94LE	S/N	02646
Oil leakage	(FAIR) · Attn			
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR) · Attn			
Oil	(FAIR) · Attn			
Exhaust Color	(FAIR) · Attn			
US EPA	YES · (NO)			
OPERATION PUMP				
Sound	(FAIR) · Attn			
Oil leakage	(FAIR) · Attn			
Power	(FAIR) · Attn			
COOLING SYSTEM				
Radiator	(FAIR) · Attn			
Oil Cooler	(FAIR) · Attn			
TRANSMISSION & TRAVEL				
T/M TYPE	(PS) · DD	DIFF. STEERING	YES · (NO)	
Transmission	(FAIR) · Attn			
Travel	(FAIR) · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · (FAIR) · DIRTY			
Operator's Seat	(FAIR) · Attn	損傷あり A LITTLE DAMAGED		
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · (None)			
BLADE & CYLINDERS				
BLADE	(FAIR) · Attn			
CYLD.(R)	(FAIR) · Attn			
CYLD.(L)	(FAIR) · Attn			
TILT CYLD	(FAIR) · Attn			
ANGLE CYLD	(FAIR) · Attn			

UNDERCARRIAGE		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	FAIR · Attn		
EQUALIZER BAR	FAIR · Attn		
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。