

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/27	MAKE	YANMAR	MODEL	B12-2
SERIAL	21450B		STAMP	21450B	
HR METER	2882	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	230R	

ENGINE : MODEL		3TNA72L	S/N	B1143
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn	とても弱い VERY WEAK POWER	
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn	パワーが弱い WEAK POWER	
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN		FAIR	DIRTY
Operator's Seat	FAIR	Attn	なし NOTHING	
Glasses	FAIR	Attn		
AirCon	A/C		H/C	H only ・ C only ・ None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	にじみあり OIL OOZING	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	コンクリート付着あり CONCRETE STAINS	
BKT Cylinder	FAIR	Attn	傷小 SCRATCHED	

UNDERCARRIAGE : See Photos.写真参照

RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)3

COMMENT
両側走行モーター油漏れ小 TRAVEL MOTORS: OIL LEAKING

BKTSTD / SLOPE / NARROW / SKELETON / OTHER()
LeverLONG ▪ WRIST
MultiMULTI ▪ 2 ▪ NO
ARM-CRANEYES ▪ NO
BLADEYES ▪ NO
OFFSETYES ▪ NO
OFFSET CylinderFAIR ▪ Attn
PipingYES ▪ NO Breaker only ▪ Multi

COMMENT
E/G回転をフルスロットルにしないと動かない
NEED TO OPERATE WITH FULL THROTTLE
スイングシリンダー油漏れあり SWING CYLINDER: OIL LEAKING
腹下油漏れあり BOTTOM: OIL LEAKING

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。