

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/5	MAKE	KOMATSU	MODEL	PC138US-8
SERIAL	23547		STAMP	KMTPC189V01023547	
HR METER	9475	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE :		MODEL	4D95LE-5	S/N	505695
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE *1		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn	ガタあり SWING: LOOSE		
Travel	FAIR	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn	破れあり CUT		
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None
BOOM / ARM / BKT					
Boom	FAIR	Attn			
Boom Cylinder	FAIR	Attn			
Arm	FAIR	Attn			
Arm Cylinder	FAIR	Attn			
BKT	FAIR	Attn	ガタあり LOOSE		
BKT Cylinder	FAIR	Attn			

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT					
左右トラックローラーガタあり SOME TRACK ROLLERS: LOOSE					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER ()				
Lever	LONG • (WRIST)				
Multi	(MULTI) • 2 • NO				
ARM-CRANE	YES • (NO)				
BLADE	(YES) • NO				
OFFSET	YES • (NO)				
OFFSET Cylinder	FAIR • Attn				
Piping	(YES) • NO	Breaker only • (Multi)			
COMMENT					
右Fサイドカバーラッチ掛からない					
FRONT RIGHT COVER LATCH: MALFUNCTION					
ブーム横ホースひび割れあり					
SOME HOSES AROUND LOWER PART OF BOOM: CRACKED					
ウインチ付 W/WINCH MAKE: NANSEI PWF-25-115-2098					
*1 オイル吐出しあり OIL SPURTING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。