

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/9/5	MAKE	YANMAR	MODEL	VIO50-5
SERIAL	50732B		STAMP	50732B	
HR METER	3955	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	400R	

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	(YES) · NO	
MAIN PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · (Attn)	油漏れ小 OIL LEAKING
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
BOOM / ARM / BKT		
Boom	(FAIR) · Attn	
Boom Cylinder	(FAIR) · Attn	
Arm	(FAIR) · Attn	
Arm Cylinder	(FAIR) · Attn	
ATTACHMENT	(FAIR) · Attn	
BKT Cylinder	(FAIR) · Attn	

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	STD (SLOPE)	NARROW / SKELETON / OTHER()
Lever	LONG · (WRIST)	
Multi	(MULTI) · 2 · NO	
ARM-CRANE	(YES) · NO	*1
BLADE	(YES) · NO	
OFFSET	YES · (NO)	
OFFSET Cylinder	FAIR · Attn	
Piping	YES · (NO)	Breaker only · Multi
COMMENT		
*1 クレーンモニター故障あり MONITOR: MALFUNCTION		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。