

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/9/5	MAKE	YANMAR	MODEL	VIO50-5
SERIAL	50802B			STAMP	50802B
HR METER	8331	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	400R

ENGINE : MODEL		S/N	41140
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	☒ YES	NO	
MAIN PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	油漏れ小 OIL LEAKING
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
OPERATING SYSTEM			
Swing	☒ FAIR	Attn	
Travel	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN ・ ☒ FAIR	DIRTY	
Operator's Seat	☒ FAIR	Attn	破れあり CUTS
Glasses	☒ FAIR	Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・ ☒ None		
BOOM / ARM / BKT			
Boom	☒ FAIR	Attn	ガタあり LOOSE
Boom Cylinder	☒ FAIR	Attn	
Arm	☒ FAIR	Attn	
Arm Cylinder	☒ FAIR	Attn	
ATTACHMENT	☒ FAIR	Attn	ガタあり LOOSE
BKT Cylinder	☒ FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD ☒ SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG ・ ☒ WRIST
Multi	☒ MULTI ・ 2 ・ NO
ARM-CRANE	YES ・ ☒ NO
BLADE	☒ YES ・ NO
OFFSET	YES ・ ☒ NO
OFFSET Cylinder	FAIR ・ Attn
Piping	☒ YES ・ NO Breaker only ☒ Multi
COMMENT	
ワンタッチ付 W/ONE-TOUCH	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。