

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/25	MAKE	KOMATSU	MODEL	PC03-2
SERIAL	16278		STAMP	16278	
HR METER	1030	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>		SHOE	185R	

ENGINE : MODEL GX360K1 S/N	
Oil leakage	<u>FAIR</u> ・ Attn
Blow-By	<u>FAIR</u> ・ Attn A LITTLE ・ MIDDLE ・ SEVERE
Sound	<u>FAIR</u> ・ Attn
Oil	<u>FAIR</u> ・ Attn
Exhaust Color	<u>FAIR</u> ・ Attn
US EPA	YES ・ <u>NO</u>
MAIN PUMP	
Sound	<u>FAIR</u> ・ Attn
Oil leakage	<u>FAIR</u> ・ Attn
Power	<u>FAIR</u> ・ Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> ・ Attn
Oil Cooler	<u>FAIR</u> ・ Attn
OPERATING SYSTEM	
Swing	<u>FAIR</u> ・ <u>Attn</u> ガタあり SWING: LOOSE
Travel	<u>FAIR</u> ・ Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN ・ <u>FAIR</u> ・ DIRTY
Operator's Seat	<u>FAIR</u> ・ <u>Attn</u> 破れありバックレスト欠 CUTS, BACKREST: MISSING
Glasses	<u>FAIR</u> ・ Attn
AirCon	A/C ・ H/C ・ H only ・ C only ・ <u>None</u>
BOOM / ARM / BKT	
Boom	<u>FAIR</u> ・ Attn
Boom Cylinder	<u>FAIR</u> ・ Attn
Arm	<u>FAIR</u> ・ Attn
Arm Cylinder	<u>FAIR</u> ・ Attn
ATTACHMENT	<u>FAIR</u> ・ Attn
BKT Cylinder	<u>FAIR</u> ・ Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG ・ <u>WRIST</u>
Multi	MULTI ・ 2 ・ <u>NO</u>
ARM-CRANE	YES ・ <u>NO</u>
BLADE	<u>YES</u> ・ NO
OFFSET	YES ・ <u>NO</u>
OFFSET Cylinder	<u>FAIR</u> ・ Attn
Piping	YES ・ <u>NO</u> Breaker only ・ Multi
COMMENT	
スイングガタあり SWING PART: LOOSE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。