

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/17	MAKE	KOMATSU	MODEL	PC200-8N1
SERIAL	313064		STAMP	UNREADABLE	
HR METER	23512 HR		YEAR	2008 YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	800G	

ENGINE :		MODEL	6D107E-1	S/N	26521477
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn	ガタあり SWING: LOOSE		
Travel	FAIR	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn	破れあり CUT		
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None
BOOM / ARM / BKT					
Boom	FAIR	Attn	補修跡あり REPAIRED		
Boom Cylinder	FAIR	Attn			
Arm	FAIR	Attn			
Arm Cylinder	FAIR	Attn			
ATTACHMENT	FAIR	Attn	ガタあり LOOSE		
BKT Cylinder	FAIR	Attn			

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
COMMENT			
左右ピンブッシュ割れ多数あり MANY PIN BUSHES: BROKEN			
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()		
Lever	LONG ・ WRIST		
Multi	MULTI ・ 2 ・ NO		
ARM-CRANE	YES ・ NO	E50表示あり "E50" ERROR DISPLAY	
BLADE	YES ・ NO		
OFFSET	YES ・ NO		
OFFSET Cylinder	FAIR ・ Attn		
Piping	YES ・ NO	Breaker only ・ Multi	
COMMENT			
A/Cエラー表示あり A/C ERROR DISPLAY			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。