

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/4	MAKE	KOMATSU	MODEL	PC450LC-11N0
SERIAL	85781			STAMP	KMTPC251PLC085781
HR METER	13261	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		S/N
Oil leakage	FAIR • <u>Attn</u>	油汚れあり OIL STAINS
Blow-By	FAIR • <u>Attn</u>	A LITTLE • <u>MIDDLE</u> • SEVERE
Sound	<u>FAIR</u> • Attn	
Oil	<u>FAIR</u> • Attn	
Exhaust Color	<u>FAIR</u> • Attn	
US EPA	YES • <u>NO</u>	
MAIN PUMP		
Sound	<u>FAIR</u> • Attn	
Oil leakage	<u>FAIR</u> • Attn	
Power	<u>FAIR</u> • Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> • Attn	
Oil Cooler	<u>FAIR</u> • Attn	
OPERATING SYSTEM		
Swing	<u>FAIR</u> • Attn	
Travel	<u>FAIR</u> • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY	
Operator's Seat	<u>FAIR</u> • Attn	
Glasses	<u>FAIR</u> • Attn	
AirCon	<u>A/C</u> • H/C • H only • C only • None	
BOOM / ARM / BKT		
Boom	<u>FAIR</u> • Attn	
Boom Cylinder	<u>FAIR</u> • Attn	
Arm	<u>FAIR</u> • Attn	
Arm Cylinder	<u>FAIR</u> • Attn	
BKT	<u>FAIR</u> • Attn	
BKT Cylinder	FAIR • <u>Attn</u>	油漏れ小 OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
底板周り油漏れあり BOTTOM: OIL LEAKING	
BKT	STD / SLOPE / NARROW / SKELETON • <u>OTHER</u> (MAGNET)
Lever	LONG • <u>WRIST</u>
Multi	MULTI • 2 • <u>NO</u>
ARM-CRANE	YES • <u>NO</u>
BLADE	YES • <u>NO</u>
OFFSET	YES • <u>NO</u>
OFFSET Cylinder	FAIR • Attn
Piping	YES • <u>NO</u> Breaker only • Multi
COMMENT	
エレベータCAB ELEVATOR CAB	
L03、L01表示あり(KDPF系統異常、尿素SCRシステム異常)	
"L03" & "L01" ERRORS DISPLAY	
FOR DIESEL PARTICULATE FILTER SYSTEM & UREA SCR SYSTEM	
付属品: ヘッドガード、手すり、ステップ	
HEAD GUARD, HANDRAILS, & STEPS AS SPARE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。