

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/8/1	MAKE	HITACHI	MODEL	KH180-3
SERIAL No.	PLATE :	242-1222	STAMP	242-1222	
HR METER	1689 + UNKNOWN	HR	SHOE	760FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	FAIR · ☒ Attn	*1
Blow-By	FAIR · ☒ Attn	A LITTLE · MIDDLE · ☒ SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · NG	未確認 NOT CHECKED
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 9m × 1, 6m × 3, 3m × 1	
BOOM TOTAL	43m	
TOP SHEAVE	☒ YES · NO	
JIB	15m	
TOP, BOTTOM, 3m × 3		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	☒ FAIR · Attn	破れあり CUTS
Glasses	☒ FAIR · Attn	
AirCon	A/C · H/C · ☒ H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
キャタたるみあり TRACK LINKS: WORN		
WEIGHT	2	
HOOK	50t, 15t, BALL	
LIFTER	YES · ☒ NO	
COMMENT		
HRメーター交換済 HR METER: REPLACED		
フリーフォール付 FREE FALL: YES		
*1 E/G下部にじみ、ターボ付近油漏れあり		
*1 BOTTOM: OIL OOZING, AROUND TURBO: OIL LEAKING		
@NARITA YARD		
BOOM: TOP, BOTTOM, 9m × 1, 50t HOOK		
@SAKURA YARD		
BOOM: 6m × 3, 3m × 1		
HOOK: 15t, BALL		
JIB: TOP, BOTTOM, 3m × 3		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。