

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/8/8	MAKE	KCM	MODEL	85ZV-2
SERIAL	85C5-0258		STAMP	85C5-0258	
HR METER	29419 / 29525	HR	Odometer	78690	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	23.5-25	

ENGINE : MODEL		S/N	26861759
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	YES	☒ NO	
OPERATION PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	☒ PS	DD	
Transmission	☒ FAIR	Attn	
Travel	☒ FAIR	Attn	
FOOT BRAKE	☒ FAIR	Attn	
PARKING BRAKE	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	☒ DIRTY
Operator's Seat	☒ FAIR	Attn	
Glasses	☒ FAIR	Attn	
AirCon	☒ A/C	H/C · H only · C only · None	
FRONT & CYLINDERS			
Arm	☒ FAIR	Attn	
Bell crank	☒ FAIR	Attn	
Bucket	FAIR	Attn	*1
Articulate	FAIR	Attn	左右シリンダーにじみあり CYLINDERS: OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES · ☒ NO
ATTACHMENTS	
STD BKT	☒ YES · OTHER
BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO
COMMENT	
*1 シリンダー油漏れ、サビあり CYLINDER: OIL LEAKING, RUSTY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。