

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/1	MAKE	KOMATSU	MODEL	PC138US-11
SERIAL	54982		STAMP	KMTPC261VKA054982	
HR METER	3289	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL		4D95LE-7	S/N	811291
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
MAIN PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
OPERATING SYSTEM				
Swing	FAIR · Attn			
Travel	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn			
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn			
Arm	FAIR · Attn			
Arm Cylinder	FAIR · Attn			
BKT	FAIR · Attn			
BKT Cylinder	FAIR · Attn			

UNDERCARRIAGE : See Photos. 写真参照		4		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				
COMMENT				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%; padding: 5px;">BKT</td> <td style="padding: 5px;"> ☒ STD / ☐ SLOPE / ☐ NARROW / ☐ SKELETON / ☐ OTHER (</td> </tr> </table>			BKT	☒ STD / ☐ SLOPE / ☐ NARROW / ☐ SKELETON / ☐ OTHER (
BKT	☒ STD / ☐ SLOPE / ☐ NARROW / ☐ SKELETON / ☐ OTHER (			
Lever	LONG ☐ ☒ WRIST			
Multi	MULTI ☐ 2 ☒ NO			
ARM-CRANE	☒ YES ☐ NO			
BLADE	YES ☐ ☒ NO			
OFFSET	YES ☐ ☒ NO			
OFFSET Cylinder	FAIR ☐ Attn			
Piping	☒ YES ☐ NO Breaker only ☒ Multi			
COMMENT				
L01尿素SCRシステム異常表示あり				
“L01” ERRORS DISPLAY FOR UREA SCR SYSTEM				
アーム、バケットを全開で伸ばすとL04システム異常表示あり(戻すと消える)				
“L04” ERROR DISPLAY FOR SYSTEM WHEN FULLY OPENING ARM & BUCKET				
(ERROR CODE: DISAPPEARING WHEN DRAWING ARM & BUCKET)				
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%; padding: 5px;">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center; vertical-align: middle; padding: 5px;">4</td> </tr> </table>			RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4			

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。