

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/21	MAKE	SUMITOMO	MODEL	SH225X-3B
SERIAL	SMT225X3L00SD7332		STAMP	SMT225X3L00SD7332	
HR METER	7144	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G PADS	

ENGINE : MODEL						4HK1			S/N			708227		
Oil leakage		(FAIR)			Attn									
Blow-By		(FAIR)			A LITTLE · MIDDLE · SEVERE									
Sound		(FAIR)			Attn									
Oil		(FAIR)			Attn									
Exhaust Color		(FAIR)			Attn									
US EPA		YES	(NO)											
MAIN PUMP														
Sound		(FAIR)			Attn									
Oil leakage		(FAIR)			Attn									
Power		(FAIR)			Attn									
COOLING SYSTEM														
Radiator		(FAIR)			Attn									
Oil Cooler		(FAIR)			Attn									
OPERATING SYSTEM														
Swing		(FAIR)			Attn									
Travel		(FAIR)			Attn									
INTERIOR						See Photos. 写真参照								
INTERIOR COND.		CLEAN	(FAIR)		DIRTY									
Operator's Seat		(FAIR)			破れあり HUGE CUT									
Glasses		(FAIR)			Attn									
AirCon		A/C			H/C			H only			C only			None
BOOM / ARM / BKT														
Boom		(FAIR)			Attn									
Boom Cylinder		(FAIR)			Attn									
Arm		(FAIR)			Attn									
Arm Cylinder		(FAIR)			Attn									
ATTACHMENT		(FAIR)			Attn									
BKT Cylinder		(FAIR)			Attn									

UNDERCARRIAGE :										See Photos. 写真参照									
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)															2				
COMMENT																			
足周りコンクリート付着あり CONCRETE STAINS																			
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER()																		
Lever	LONG · (WRIST)																		
Multi	(MULTI) · 2 · NO																		
ARM-CRANE	(YES) · NO																		
BLADE	(YES) · NO																		
OFFSET	YES · (NO)																		
OFFSET Cylinder	FAIR · Attn																		
Piping	YES · (NO) Breaker only · Multi																		
COMMENT																			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)															3				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。