

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/19	MAKE	KOMATSU	MODEL	PC128US-8
SERIAL	32181		STAMP	KMTPC189J01032181	
HR METER	6413	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL 4D95LE-5 S/N 547788					
Oil leakage	(FAIR)	Attn			
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR)	Attn			
Oil	(FAIR)	Attn			
Exhaust Color	(FAIR)	Attn			
US EPA	YES	(NO)			
MAIN PUMP					
Sound	(FAIR)	Attn			
Oil leakage	(FAIR)	Attn			
Power	(FAIR)	Attn			
COOLING SYSTEM					
Radiator	(FAIR)	Attn			
Oil Cooler	(FAIR)	Attn			
OPERATING SYSTEM					
Swing	(FAIR)	Attn			
Travel	(FAIR)	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	·	(FAIR)	·	DIRTY
Operator's Seat	(FAIR)	Attn	破れあり TORN		
Glasses	(FAIR)	Attn			
AirCon	(A/C)	·	H/C	·	H only · C only · None
BOOM / ARM / BKT					
Boom	(FAIR)	Attn	ガタあり LOOSE		
Boom Cylinder	(FAIR)	Attn			
Arm	(FAIR)	Attn			
Arm Cylinder	(FAIR)	Attn			
ATTACHMENT	(FAIR)	Attn	ガタあり LOOSE		
BKT Cylinder	(FAIR)	Attn			

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4	
COMMENT			
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG	·	(WRIST)
Multi	(MULTI)	· 2 · NO	
ARM-CRANE	YES	·	(NO)
BLADE	(YES)	· NO	
OFFSET	YES	·	(NO)
OFFSET Cylinder	FAIR	· Attn	
Piping	(YES)	· NO	Breaker only · Multi
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。