

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/25	MAKE	KOMATSU	MODEL	PC128US-8
SERIAL	32117			STAMP	KMTPC189C01032117
HR METER	6844	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL 4D95LE-5 S/N 547591

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR Attn 破れあり TORN
Glasses	FAIR Attn
AirCon	A/C · H/C · H only · C only · None

BOOM / ARM / BKT

Boom	FAIR Attn	ガタ大 MUCH LOOSE
Boom Cylinder	FAIR Attn	右側油漏れ小 RIGHT CYLINDER: OIL LEAKING
Arm	FAIR Attn	
Arm Cylinder	FAIR Attn	
ATTACHMENT	FAIR Attn	
BKT Cylinder	FAIR Attn	サビあり RUSTY

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

COMMENT

.....

.....

.....

.....

BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only Multi

COMMENT

.....

.....

.....

.....

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。