

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/21	MAKE	HITACHI	MODEL	ZX75US-3
SERIAL	HCM1P300K00064139			STAMP	HCM1P300K00064139
HR METER	3890	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	450G PADS

ENGINE : MODEL S/N Oil leakage FAIR · Attn Blow-By FAIR · Attn A LITTLE MIDDLE SEVERE Sound FAIR · Attn Oil FAIR · Attn Exhaust Color FAIR · Attn US EPA YES · NO MAIN PUMP Sound FAIR · Attn Oil leakage FAIR · Attn にじみあり OIL OOZING Power FAIR · Attn COOLING SYSTEM Radiator FAIR · Attn Oil Cooler FAIR · Attn OPERATING SYSTEM Swing FAIR · Attn ガタあり SWING: LOOSE Travel FAIR · Attn INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · FAIR · DIRTY Operator's Seat FAIR · Attn Glasses FAIR · Attn AirCon A/C · H/C · H only · C only · None BOOM / ARM / BKT Boom FAIR · Attn Boom Cylinder FAIR · Attn 油漏れ小 OIL LEAKING Arm FAIR · Attn Arm Cylinder FAIR · Attn ATTACHMENT FAIR · Attn ガタあり LOOSE BKT Cylinder FAIR · Attn	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3 COMMENT BKT STD / SLOPE / NARROW / SKELETON / OTHER () Lever LONG · WRIST Multi MULTI · 2 · NO ARM-CRANE YES · NO BLADE YES · NO OFFSET YES · NO OFFSET Cylinder FAIR · Attn Piping YES · NO Breaker only · Multi COMMENT 動作中コントロールバルブ周りから唸るような異音あり AROUND CONTROL VALVE: NOISES LIKE A LOW GROWL DURING OPERATING RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
---	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。