

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/7	MAKE	IHI	MODEL	30VZ
SERIAL	WT001250		STAMP	WT001250	
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	300R	

ENGINE : MODEL		3TNV84	S/N	40135
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	ガタあり SWING: LOOSE	
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn	CNP欠 SKYLIGHT: MISSING	
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	にじみあり OIL OOZING	
Arm	FAIR	Attn	ガタあり LOOSE	
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照					
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT シュー摩耗あり RUBBER TRACKS: WORN					
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER()				
Lever	LONG ・ (WRIST)				
Multi	MULTI ・ 2 ・ (NO)				
ARM-CRANE	(YES) ・ NO	*1			
BLADE	(YES) ・ NO				
OFFSET	(YES) ・ NO	*2			
OFFSET Cylinder	(FAIR) ・ Attn				
Piping	YES ・ (NO)	Breaker only	・ Multi		
COMMENT モニター：水混入あり、見えない INSIDE OF MONITOR PANEL: CONDENSATION, UNREADABLE *1 クレーンモード入らない CRANE MODE: UNABLE TO TURN ON *2 ペダル固い、戻り悪い、ガタあり *2 PEDAL: STIFF, HARD TO RETURN, LOOSE					
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。