

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/22	MAKE	KOMATSU	MODEL	PC128UU-2
SERIAL	5677			STAMP	PC128-5677
HR METER	4255	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G PADS

ENGINE : MODEL		4D102E-1	S/N	26293988
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn	*1	
AirCon	A/C	H/C	H only	C only
None				
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	ガタ大 MUCH LOOSE	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG ▪ WRIST
Multi	MULTI ▪ 2 ▪ NO
ARM-CRANE	YES ▪ NO
BLADE	YES ▪ NO
OFFSET	YES ▪ NO
OFFSET Cylinder	FAIR ▪ Attn
Piping	YES ▪ NO Breaker only ▪ Multi
COMMENT	
付属品:スタンダードバケット STANDARD BUCKET AS SPARE	
*1 左サイドガラスひび割れあり LEFT SIDE GLASS: CRACKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。