

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/25	MAKE	KOMATSU	MODEL	PC128US-10
SERIAL	42564		STAMP	KMTPC245KFA042564	
HR METER	8712	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL						4D95LE-6 S/N							706963							
Oil leakage		(FAIR)			Attn															
Blow-By		(FAIR)			Attn		A LITTLE · MIDDLE · SEVERE													
Sound		(FAIR)			Attn															
Oil		(FAIR)			Attn															
Exhaust Color		(FAIR)			Attn															
US EPA		YES	(NO)																	
MAIN PUMP																				
Sound		(FAIR)			Attn															
Oil leakage		(FAIR)			Attn															
Power		(FAIR)			Attn															
COOLING SYSTEM																				
Radiator		(FAIR)			Attn															
Oil Cooler		(FAIR)			Attn															
OPERATING SYSTEM																				
Swing		(FAIR)			Attn															
Travel		(FAIR)			Attn															
INTERIOR See Photos. 写真参照																				
INTERIOR COND.		(CLEAN)					FAIR · DIRTY													
Operator's Seat		(FAIR)			Attn															
Glasses		(FAIR)			Attn															
AirCon		A/C	· H/C		· H only · C only · None															
BOOM / ARM / BKT																				
Boom		(FAIR)			Attn															
Boom Cylinder		(FAIR)			Attn															
Arm		(FAIR)			Attn															
Arm Cylinder		(FAIR)			Attn															
ATTACHMENT		(FAIR)			Attn															
BKT Cylinder		(FAIR)			Attn															
UNDERCARRIAGE :																				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																		See Photos. 写真参照		
COMMENT																				
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()																		
Lever	LONG	· WRIST																		
Multi	MULTI · 2	· NO																		
ARM-CRANE	YES	· NO																		
BLADE	YES	· NO																		
OFFSET	YES	· NO																		
OFFSET Cylinder	FAIR	· Attn																		
Piping	YES	· NO Breaker only · Multi																		
COMMENT																				
車内にガラス片あり GLASS FRAGMENTS: BEING IN CAB																				
L01エラー表示あり(A/C系統異常)																				
“L01” ERROR DISPLAY FOR A/C SYSTEM																				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																		3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。