

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/18	MAKE	KOBELCO	MODEL	SK75UR-3E
SERIAL	YR05-05605			STAMP	YR05-05605
HR METER	9233	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	450G PADS

ENGINE : MODEL		4JG1	S/N	229142
Oil leakage	☒ FAIR	Attn		
Blow-By	☒ FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	☒ FAIR	Attn		
Oil	☒ FAIR	Attn		
Exhaust Color	☒ FAIR	Attn		
US EPA	☒ YES	NO		
MAIN PUMP				
Sound	☒ FAIR	Attn		
Oil leakage	☒ FAIR	Attn		
Power	☒ FAIR	Attn		
COOLING SYSTEM				
Radiator	☒ FAIR	Attn		
Oil Cooler	☒ FAIR	Attn		
OPERATING SYSTEM				
Swing	☒ FAIR	Attn	*1	
Travel	☒ FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	☒ DIRTY	
Operator's Seat	☒ FAIR	Attn	破れあり HUGE CUTS	
Glasses	☒ FAIR	Attn		
AirCon	☒ A/C	H/C	H only	C only
BOOM / ARM / BKT				
Boom	☒ FAIR	Attn		
Boom Cylinder	☒ FAIR	Attn		
Arm	☒ FAIR	Attn	へコミあり DENT	
Arm Cylinder	☒ FAIR	Attn		
BKT	☒ FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	☒ FAIR	Attn	油漏れ小 OIL LEAKING	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
旋回モーター下油漏れ小 BOTTOM OF SWING MOTOR: OIL LEAKING	
ポンプ下周り油汚れあり BOTTOM OF PUMP: OIL STAINS	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	MULTI · 2 · ☒ NO
ARM-CRANE	☒ YES · NO *2
BLADE	☒ YES · NO
OFFSET	☒ YES · NO
OFFSET Cylinder	☒ FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
「E/Gオイルをかえてください」表示あり	
WARNING DISPLAY FOR ENGINE OIL CHANGE	
A/Cベルト欠 A/C: NO BELT	
*1 ガタあり、レバー倒してから0.5秒くらいに動く	
*1 SWING: LOOSE, DULL MOVING ABOUT HALF A SECOND LATE	
*2 クレーン画面表示されない、バケットロックOK	
*2 LOAD INDICATOR: NOT DISPLAYING, ABLE TO LOCK THE BUCKET	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。