

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2025/7/25	MAKE	NKK	MODEL	NUL070R
SERIAL No.	PLATE : 7NUR052			STAMP : 7R052	
HR METER	6090	HR	Odometer	km	YEAR YR
CHASSIS	MODEL			No.	
SHOE	230R			TIRE SIZE	
MAX HIGHT	6.8 m			MAX WEIGHT	150 kg

ENGINE : MODEL S/N	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	YES ☒ NO
OPERATION PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ AT · MT No. OF GEARS — GEARS
Transmission	☒ FAIR · Attn
4WD	4WD · 2WD
Travel	☒ FAIR · Attn
Swing	☒ FAIR · Attn
FOOT BRAKE	☒ FAIR · Attn
PARKING BRAKE	☒ FAIR · Attn
BOOM	
No. of Section	2 SECTIONS
DERRICKING CYL.	☒ FAIR · Attn
EXTENSION CYL.	☒ FAIR · Attn

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn
Glasses	☒ FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
バケット内フットペダルS/W押された状態のまま	
FOOT PEDAL IN BUCKET: STAYING AT THE PRESSED POSITION	
OUTRIGGERS X · H	
OUTRIGGERS COND.	☒ FAIR · Attn
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。