

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/4	MAKE	IHI	MODEL	40VX
SERIAL	WV000154			STAMP	WV000154
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE			SHOE	400G PADS

ENGINE : MODEL 4TNV88 S/N 49919	
Oil leakage	<u>FAIR</u> ・ Attn
Blow-By	<u>FAIR</u> ・ Attn A LITTLE ・ MIDDLE ・ SEVERE
Sound	<u>FAIR</u> ・ Attn
Oil	<u>FAIR</u> ・ Attn
Exhaust Color	<u>FAIR</u> ・ Attn
US EPA	<u>YES</u> ・ NO
MAIN PUMP	
Sound	<u>FAIR</u> ・ Attn
Oil leakage	<u>FAIR</u> ・ Attn
Power	<u>FAIR</u> ・ Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> ・ Attn
Oil Cooler	<u>FAIR</u> ・ Attn
OPERATING SYSTEM	
Swing	<u>FAIR</u> ・ Attn ガタあり SWING: LOOSE
Travel	<u>FAIR</u> ・ Attn HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN ・ <u>FAIR</u> ・ DIRTY
Operator's Seat	<u>FAIR</u> ・ Attn 破れあり TINY CUTS
Glasses	FAIR ・ Attn
AirCon	A/C ・ H/C ・ H only ・ C only ・ <u>None</u>
BOOM / ARM / BKT	
Boom	<u>FAIR</u> ・ Attn スイングガタあり SWING PART: LOOSE
Boom Cylinder	<u>FAIR</u> ・ Attn
Arm	<u>FAIR</u> ・ Attn 補強あり REINFORCED
Arm Cylinder	FAIR ・ <u>Attn</u> 油漏れ小 OIL LEAKING
BKT	<u>FAIR</u> ・ Attn 曲がりあり DISTORTED
BKT Cylinder	<u>FAIR</u> ・ Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT <u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG ・ <u>WRIST</u>
Multi	<u>MULTI</u> ・ 2 ・ NO
ARM-CRANE	YES ・ <u>NO</u>
BLADE	<u>YES</u> ・ NO
OFFSET	YES ・ <u>NO</u>
OFFSET Cylinder	FAIR ・ Attn
Piping	<u>YES</u> ・ NO Breaker only ・ <u>Multi</u>
COMMENT	
モニター不良 MONITOR: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。