

**INSPECTION SHEET 検品書**  
**LIFTING PLATFORM 高所作業車**

INSPECTION DATE	2025/8/4	MAKE	AICHI	MODEL	SK200
SERIAL No.	PLATE : 520557			STAMP : 520557	
HR METER	2928	HR	Odometer	524886	km
YEAR	YR				
CHASSIS	MODEL BDG-XZU434M			No. XZU434-1000681	
SHOE				TIRE SIZE	225/80R17.5
MAX HIGHT	20.0			m	
MAX WEIGHT	200			kg	

<b>ENGINE : MODEL S/N</b>	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
US EPA	YES <input checked="" type="radio"/> NO
<b>OPERATION PUMP</b>	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
<b>COOLING SYSTEM</b>	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
<b>TRANSMISSION &amp; TRAVEL</b>	
T/M TYPE	AT <input checked="" type="radio"/> MT
No. OF GEARS	6 GEARS
Transmission	<input checked="" type="radio"/> FAIR · Attn
4WD	4WD <input checked="" type="radio"/> 2WD
Travel	<input checked="" type="radio"/> FAIR · Attn
Swing	<input checked="" type="radio"/> FAIR · Attn
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn
<b>BOOM</b>	
No. of Section	4 SECTIONS
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · Attn
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · Attn

<b>INTERIOR See Photos. 写真参照</b>	
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	<input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR
<b>COMMENT</b>	
OUTRIGGERS X · <input checked="" type="radio"/> H	
OUTRIGGERS COND.	FAIR · <input checked="" type="radio"/> Attn *1
<b>COMMENT</b>	
作動油タンクホース付近油漏れ小	
AROUND HYDRAULIC OIL TANK HOSE: OIL LEAKING	
*1 左R横シリンダー油圧ホース付近油漏れあり	
*1 AROUND REAR LEFT SLIDE CYLINDER HOSE: OIL LEAKING	
<b>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b>	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。