

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/26	MAKE	KOMATSU	MODEL	PC75UU-2
SERIAL	11040			STAMP	11040
HR METER	E6080	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	450G PADS

ENGINE : MODEL		S/N		UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage	FAIR • Attn			RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE		COMMENT	
Sound	FAIR • Attn				
Oil	FAIR • Attn				
Exhaust Color	FAIR • Attn				
US EPA	YES • NO				
MAIN PUMP				BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Sound	FAIR • Attn			Lever	LONG • WRIST
Oil leakage	FAIR • Attn			Multi	MULTI • 2 • NO
Power	FAIR • Attn			ARM-CRANE	YES • NO
COOLING SYSTEM				BLADE	YES • NO
Radiator	FAIR • Attn			OFFSET	YES • NO *2
Oil Cooler	FAIR • Attn			OFFSET Cylinder	FAIR • Attn
OPERATING SYSTEM				Piping	YES • NO Breaker only • Multi
Swing	FAIR • Attn			COMMENT	
Travel	FAIR • Attn			HRメーターストップ HR METER: STOPPED	
INTERIOR See Photos. 写真参照				計器類動かない INDICATOR: MALFUNCTION	
INTERIOR COND.	CLEAN • FAIR • DIRTY			電気エラーあり WARNING LAMP FOR ELECTRIC SYSTEM: ON	
Operator's Seat	FAIR • Attn			運転席ドア開けたままの状態、ドア上部外れあり(要写真参照)	
Glasses	FAIR • Attn			DOOR: UNABLE TO SHUT, UPPER GUIDE RAIL: NOT ATTACHED	
AirCon	A/C • H/C • H only • C only • None			(FIXED AT OPENED POSITION WITH WIRES & SOME BELT)	
BOOM / ARM / BKT				*1 穴あり、コンクリート付着小 MUCH CRACKED, HOLE, CONCRETE STAINS	
Boom	FAIR • Attn			*2 干渉防止不良 ANTI-INTERFERENCE SYSTEM: MALFUNCTION	
Boom Cylinder	FAIR • Attn				
Arm	FAIR • Attn				
Arm Cylinder	FAIR • Attn				
ATTACHMENT	FAIR • Attn	*1			
BKT Cylinder	FAIR • Attn	傷小 SCRATCHED		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。