

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/17	MAKE	CAT	MODEL	336FXE
SERIAL	CAT0336FENAJ10028		STAMP	CAT0336FENAJ10028	
HR METER	8897 / 8904	HR	YEAR	2017	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE :		MODEL	C9.3	S/N	SYE19358
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn			
Travel	FAIR	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN · FAIR · DIRTY				
Operator's Seat	FAIR	Attn			
Glasses	FAIR	Attn			
AirCon	A/C · H/C · H only · C only · None				
BOOM / ARM / BKT					
Boom	FAIR	Attn			
Boom Cylinder	FAIR	Attn			
Arm	FAIR	Attn			
Arm Cylinder	FAIR	Attn			
BKT	FAIR	Attn			
BKT Cylinder	FAIR	Attn			

UNDERCARRIAGE : See Photos.					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4				
COMMENT					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER())				
Lever	LONG ▪	(WRIST)			
Multi	MULTI ▪ 2 ▪	(NO)			
ARM-CRANE	YES ▪	(NO)			
BLADE	YES ▪	(NO)			
OFFSET	YES ▪	(NO)			
OFFSET Cylinder	FAIR ▪ Attn				
Piping	(YES) ▪ NO	Breaker only ▪ Multi			
COMMENT					
バックモニター不良 BACK MONITOR: MALFUNCTION					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。