

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/5	MAKE	HITACHI	MODEL	EX200-3
SERIAL	14C-80168			STAMP	14C-80168
HR METER	6105	HR	YEAR	1994	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
US EPA	YES • NO	
MAIN PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
OPERATING SYSTEM		
Swing	FAIR • Attn	*1
Travel	FAIR • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	ヘッドレスト欠、穴あり HEADREST: MISSING, HOLES
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	
BOOM / ARM / BKT		
Boom	FAIR • Attn	
Boom Cylinder	FAIR • Attn	*2
Arm	FAIR • Attn	パッチ、ガタあり PATCHED, LOOSE
Arm Cylinder	FAIR • Attn	サビ、にじみあり RUSTY, OIL Oozing
BKT	FAIR • Attn	
BKT Cylinder	FAIR • Attn	*3

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
スイベル油漏れあり SWIVEL: OIL LEAKING	
スイベル下周り油漏れあり BOTTOM OF SWIVEL: OIL LEAKING	
BKT	STD (SLOPE) NARROW / SKELETON / OTHER ()
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO *4
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi
COMMENT	
14.45mスーパーロング 14.45m SUPER LONG	
バッテリーマイナス外さないと放電する	
BATTERY: DISCHARGING	
(NEGATIVE BATTERY TERMINAL: NEED TO DISCONNECT)	
EA.2表示、ブザー音あり "EA.2" ERROR DISPLAY, WARNING SOUNDS: ON	
*1 動作遅い(パワーない?)、ガタあり	
*1 SLOW SWINGING (WEAK POWER?), SWING: LOOSE	
*2 左右サビ、にじみあり CYLINDERS: RUSTY, OIL Oozing	
*3 油漏れ、ホースひび割れあり OIL LEAKING, HOSES: CRACKED	
*4 フック欠、パケットロック掛からない、電源入るが表示が変わらない	
*4 NO HOOK, UNABLE TO LOCK THE BUCKET,	
LOAD INDICATOR: NOT WORKING (CRANE MODE: ABLE TO TURN ON)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。