

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/8/5	MAKE	TADANO	MODEL	GR-160N-3
SERIAL No.	PLATE : 526860	STAMP : T009-0321			
HR METER	12670	HR	Odometer	103515	km
TIRE SIZE	325/95R24	YEAR	YR		

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · NG	
Swing	FAIR · Attn	
Travel	FAIR · Attn	
TRANSMISSION		
Transmission	FAIR · Attn	
No. OF GEARS	3	GEARS
4WD	4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり A LITTLE DAMAGED
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
COMMENT		

BOOM							
No. of Section	6		SECTIONS				
CRACK/ENFORCEMENT	(FAIR)	▪ Attn					
DERRICKING CYL.	(FAIR)	▪ Attn					
EXTENSION CYL.	(FAIR)	▪ Attn					
JIB	(YES)	▪ NO					
JIB TYPE	(STD)	▪ PWR					
MAIN & SUB WIRE	(YES)	▪ NO					
HOO K	16t, BALL						
UNDERCARRIAGE : See Photos. 写真参照							
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							4
TIRE WEAR	(FAIR) ▪ WORN ▪ UNEVEN WEAR						
COMMENT 							
OUTRIGGERS							
OUTRIGGERS	X	▪ (H)					
OUTRIGGERS COND.	(FAIR)	▪ Attn					
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR	L ▪ R		
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR	L ▪ R		
COMMENT アクチュエータ不良(エラーコード：EA641) ACTUATOR: MALFUNCTION ("EA641" ERROR DISPLAY) フリーフォールなし FREE FALL: NO 							
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。