

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/8/5	MAKE	KOBELCO	MODEL	RK250-6
SERIAL No.	PLATE : EZ08-09078		STAMP : EZ08-9078		
HR METER	27282	HR	Odometer	78223	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · ☒ MIDDLE · ☐ SEVERE	
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · ☐ NG	
Swing	☒ FAIR · ☒ *1	
Travel	☒ FAIR · Attn	
TRANSMISSION		
Transmission	☒ FAIR · Attn	
No. OF GEARS	3 GEARS	
4WD	☒ 4WD · ☐ 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR · ☐ DIRTY	
Operator's Seat	☒ FAIR · Attn	破れあり CUTS
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · ☐ H/C · ☐ H only · ☐ C only · ☐ None	
COMMENT		

BOOM				
No. of Section	4	SECTIONS		
CRACK/ENFORCEMENT	☒ FAIR · Attn			
DERRICKING CYL.	☒ FAIR · Attn			
EXTENSION CYL.	☒ FAIR · Attn			
JIB	☒ YES · ☐ NO			
JIB TYPE	☒ STD · ☐ PWR			
MAIN & SUB WIRE	☒ YES · ☐ NO			
HOOK	25t, BALL			
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				3
TIRE WEAR	FAIR · ☒ WORN · ☐ UNEVEN WEAR			
COMMENT				
下部右横カバーへコミ大 RIGHT SIDE BUMPER: DENT				
OUTRIGGERS				
OUTRIGGERS	☒ X · ☐ H			
OUTRIGGERS COND.	☒ FAIR · Attn			
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R
COMMENT				
フリーフォール付 FREE FALL: YES				
ブーム伸縮2段・3段S/W別にあり				
W/ANOTHER TELESCOPING SWITCH FOR 2nd & 3rd BOOMS				
*1 旋回ブレーキS/W固着あり SWING BRAKE SWITCH: STUCK				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。