

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/8/5	MAKE	TADANO	MODEL	GR-250N-3
SERIAL No.	PLATE : FB7655			STAMP : T007-0846	
HR METER	UNKNOWN		HR	Odometer	UNKNOWN km
TIRE SIZE	385/95R25			YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Computer	(OK) · NG	
Swing	(FAIR) · Attn	
Travel	(FAIR) · Attn	
TRANSMISSION		
Transmission	(FAIR) · Attn	
No. OF GEARS	4 GEAR	
4WD	(4WD) · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	(A/C) · H/C · H only · C only · None	
COMMENT		

BOOM					
No. of Section		4		SECTIONS	
CRACK/ENFORCEMENT		FAIR	▪	Attn	
DERRICKING CYL.		FAIR	▪	Attn	
EXTENSION CYL.		FAIR	▪	Attn	
JIB		YES	▪	NO	
JIB TYPE		STD	▪	PWR	
MAIN & SUB WIRE		YES	▪	NO	
HOOK		25t, BALL			
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
TIRE WEAR		FAIR ▪ WORN ▪ UNEVEN WEAR			
COMMENT					
タイヤ側面傷、ひび割れあり TIRE SIDEWALLS: CUTS, CRACKED					
OUTRIGGERS					
OUTRIGGERS		X	▪	H	
OUTRIGGERS COND.		FAIR	▪	Attn	
Oil leakage (JACK CYL.)		FRONT	L ▪ R	REAR	L ▪ R
Oil leakage (SLIDE CYL.)		FRONT	L ▪ R	REAR	L ▪ R
COMMENT					
過巻コードリール巻取不良					
OVERWINDING CORD REEL: MALFUNCTION TO WIND					
フリーフォールなし FREE FALL: NO					
メーター交換歴あり INDICATOR: REPLACED					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。