

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/8/5	MAKE	KATO	MODEL	KR-25H-V7
SERIAL No.	PLATE : 5110573		STAMP : KRC005-0573		
HR METER	22097	HR	Odometer	87029	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N	
Oil leakage	FAIR • Attn		
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	FAIR • Attn		
Oil	FAIR • Attn		
Exhaust Color	FAIR • Attn		
OPERATION PUMP			
Sound	FAIR • Attn		
Oil leakage	FAIR • Attn		
Power	FAIR • Attn		
COOLING SYSTEM			
Radiator	FAIR • Attn		
Oil Cooler	FAIR • Attn		
OPERATING SYSTEM			
Computer	OK • NG		
Swing	FAIR • Attn		
Travel	FAIR • Attn		
TRANSMISSION			
Transmission	FAIR • Attn		
No. OF GEARS	4	GEARS	
4WD	4WD • 6WD		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • FAIR • DIRTY		
Operator's Seat	FAIR • Attn		
Glasses	FAIR • Attn		
AirCon	A/C • H/C • H only • C only • None		
COMMENT			

BOOM					
No. of Section		4 SECTIONS			
CRACK/ENFORCEMENT	☐ FAIR ▪ Attn				
DERRICKING CYL.	☐ FAIR ▪ Attn				
EXTENSION CYL.	☐ FAIR ▪ Attn				
JIB	☒ YES ▪ NO				
JIB TYPE	STD ▪ ☒ PWR				
MAIN & SUB WIRE	☒ YES ▪ NO				
HOOK	25t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4
TIRE WEAR	☒ FAIR ▪ WORN ▪ UNEVEN WEAR				
COMMENT					
OUTRIGGERS					
OUTRIGGERS	☒ X ▪ H				
OUTRIGGERS COND.	☐ FAIR ▪ Attn				
Oil leakage (JACK CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
COMMENT					
フリーフォールなし FREE FALL: NO					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。