

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/6	MAKE	KOMATSU	MODEL	PC45MR-5
SERIAL	30310			STAMP	KMTPC259EGE030310
HR METER	2690	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE			SHOE	400G PADS

ENGINE : MODEL		4D88E	S/N	11604
Oil leakage	<u>FAIR</u> • Attn			
Blow-By	<u>FAIR</u> • Attn	A LITTLE • MIDDLE • SEVERE		
Sound	<u>FAIR</u> • Attn			
Oil	<u>FAIR</u> • Attn			
Exhaust Color	<u>FAIR</u> • Attn			
US EPA	<u>YES</u> • NO			
MAIN PUMP				
Sound	<u>FAIR</u> • Attn			
Oil leakage	<u>FAIR</u> • Attn			
Power	<u>FAIR</u> • Attn			
COOLING SYSTEM				
Radiator	<u>FAIR</u> • Attn			
Oil Cooler	<u>FAIR</u> • Attn			
OPERATING SYSTEM				
Swing	<u>FAIR</u> • Attn			
Travel	<u>FAIR</u> • Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY			
Operator's Seat	<u>FAIR</u> • Attn			
Glasses	FAIR • Attn			
AirCon	A/C • H/C • H only • C only • <u>None</u>			
BOOM / ARM / BKT				
Boom	<u>FAIR</u> • Attn			
Boom Cylinder	FAIR • <u>Attn</u>	油漏れあり OIL LEAKING		
Arm	<u>FAIR</u> • Attn			
Arm Cylinder	<u>FAIR</u> • Attn			
BKT	<u>FAIR</u> • Attn			
BKT Cylinder	<u>FAIR</u> • Attn			

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • <u>WRIST</u>
Multi	MULTI • 2 • <u>NO</u>
ARM-CRANE	YES • <u>NO</u>
BLADE	<u>YES</u> • NO
OFFSET	YES • <u>NO</u>
OFFSET Cylinder	FAIR • Attn
Piping	YES • <u>NO</u> Breaker only • Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。