INSPECTION SHEET 検品書 CRAWLER CRANE クローラクレーン

INSPECTIO	N DATE	2025/8/27	MAKE		SUMITOMO	MODEL	SC800-2	
SERIAL No.	o. PLATE: SC080-1089			STAMP		SC080-1089		
HR METER	42	57 HR	SHOE	8	B00FLAT	YEAR		YR
ENGINE :	MODEL	S/N	N		INTERIOR	See Photos.	写真参照	
Oil leakage FAIR · (Attr) *1					INTERIOR COND. CLEAN • FAIR • DIRTY			
Blow-By FAIR · Attr A LITTLE · MIDDLE · SEVERE					Operator's Seat FAIR Attn			
Sound FAIR · Attn					Glasses FAIR Attn			
Oil	FAIR · Attn				AirCon A/	с)- н/с	· H only · C only ·	None
Exhaust Color	r FAIR · Attn				UNDERCARRIAGE: See Photos. 写真参照			
OPERATION PUMP					RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			
Sound FAIR · Attn					COMMENT			
Oil leakage	FAIR · Attn							
Power	FAIR · Attn							
COOLING SYSTEM					WEIGHT	4		
Radiator FAIR · Attn				НООК	80t, 30t, B	80t, 30t, BALL		
Oil Cooler FAIR · Attn				FREE FALL	YES · NO	YES · NO		
OPERATING SYSTEM					LIFTER	YES · NO		
Computer OK · NG					COMMENT			
Swing	FAIR · Attn				*1 ヘッドカバー付え	丘にじみあり A	ROUND HEAD COVER: OIL (OOZING
Travel	FAIR · Attn							
воом					@NARITA YARD			
MAIN BOOM TOP, BOTTOM, 9		9m × 1, 6m × 2	2, 3m × 1	BOOM: TOP, BOTTOM, 9m×1, 6m×1				
BOOM TOTAL 36m			80t HOOK					
TOP SHEAVE YES · NO				@SAKURA YARD				
JIB					BOOM: 6m×1, 3m×1			
					HOOK: 30t, BAI	_L		
TOWE	ER							
					PLIST of BODY (5: NO	NE 1. A LITTLE 2.	MIDDLE 2: MUCH 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。