

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/8/25	MAKE	KOBELCO	MODEL	7035
SERIAL No.	PLATE :	GL00185	STAMP	NOT FOUND	
HR METER	2770	HR	SHOE	760FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	E/Gヘッドにじみあり CYLINDER HEAD: OIL OOZING
Blow-By	FAIR ☒ Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	
OPERATION PUMP		
Sound	FAIR ☒ Attn	
Oil leakage	FAIR ☒ Attn	
Power	FAIR ☒ Attn	
COOLING SYSTEM		
Radiator	FAIR ☒ Attn	
Oil Cooler	FAIR ☒ Attn	
OPERATING SYSTEM		
Computer	OK ☒ NG	
Swing	FAIR ☒ Attn	
Travel	FAIR ☒ Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 6m × 2, 3m × 1	
BOOM TOTAL	24m	
TOP SHEAVE	YES ☒ NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · FAIR ☒ · DIRTY	
Operator's Seat	FAIR ☒ Attn	切れあり CUTS
Glasses	FAIR ☒ Attn	
AirCon	A/C · H/C · H only ☒ · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
サイドフレーム伸縮シリンダー油漏れ大、メクラあり SIDE FRAME EXTENSION CYLINDER: SEVERE OIL LEAKING (W/CAP)		
WEIGHT	2	
HOOK	35t, BALL	
FREE FALL	YES ☒ NO	
LIFTER	YES · NO ☒	
COMMENT		
ウインチドラムにじみあり WINCH DRUM: OIL OOZING		
@NARITA YARD		
BOOM: TOP, BOTTOM, 6m × 1		
HOOK: 35t, BALL		
@YOTSUKAIDO YARD		
BOOM: 6m × 1, 3m × 1		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。