

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/8/7	MAKE	CAT	MODEL	D6M	
SERIAL	5NR00372			STAMP	5NR00372	
HR METER	3530	HR	SHOE	860LGP	YEAR	YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL		3116	S/N	1CK15192
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
OPERATION PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
TRANSMISSION & TRAVEL				
T/M TYPE	PS · DD	DIFF. STEERING	YES · NO	
Transmission	FAIR · Attn			
Travel	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn			
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
BLADE & CYLINDERS				
BLADE	FAIR · Attn			
CYLD.(R)	FAIR · Attn			
CYLD.(L)	FAIR · Attn			
TILT CYLD	FAIR · Attn			
ANGLE CYLD	FAIR · Attn			

UNDERCARRIAGE		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
COMMENT 下周り油漏れあり BOTTOM: OIL LEAKING			
Ripper	MULTI ▪ S/S	Shanks	PCS
Ripper CYLD.	FAIR ▪ Attn		
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			
3			

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。