

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/8/22	MAKE	KOMATSU	MODEL	D51PX-22
SERIAL	B10404			STAMP	KMT0D080A51B10404
HR METER	6990	HR	SHOE	720LGP	YEAR 2008 YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		S/N	30920188
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	☒ YES	NO	
OPERATION PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	☒ PS	DD	DIFF. STEERING YES ☒ NO
Transmission	☒ FAIR	Attn	
Travel	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	☒ FAIR	DIRTY
Operator's Seat	☒ FAIR	Attn	
Glasses	☒ FAIR	Attn	
AirCon	☒ A/C	H/C	H only ・ C only ・ None
BLADE & CYLINDERS			
BLADE	☒ FAIR	Attn	
CYLD.(R)	☒ FAIR	Attn	
CYLD.(L)	☒ FAIR	Attn	
TILT CYLD	☒ FAIR	Attn	
ANGLE CYLD	☒ FAIR	Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
COMMENT			
Ripper	MULTI	S/S	Shanks PCS
Ripper CYLD.	FAIR	Attn	
COMMENT			
ファンベルト鳴きあり FAN BELT: NOISES			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。