

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/7/18	MAKE	KOBELCO	MODEL	SK200-9
SERIAL	YN13-70549		STAMP	YN13-70549	
HR METER	9009	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE :	MODEL	J05E	S/N
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO	ラベル破れあり STICKER: PARTLY BROKEN	

MAIN PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	

OPERATING SYSTEM

Swing	FAIR · Attn	
Travel	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり TORN
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only None

BOOM / ARM / BKT

Boom	FAIR ・ Attn	
Boom Cylinder	FAIR ・ Attn	
Arm	FAIR ・ Attn	へコミあり DENT
Arm Cylinder	FAIR ・ Attn	
BKT	FAIR ・ Attn	
BKT Cylinder	FAIR ・ Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

COMMENT

右側トラックローラーガタあり SOME RIGHT TRACK ROLLERS: LOOSE

旋回モーター下油汚れあり BOTTOM OF SWING MOTOR: OIL STAINS

BKT (STD / SLOPE / NARROW / SKELETON / OTHER())

Lever	LONG • WRIST	
-------	--------------	--

Multi	(MULTI) • 2 • NO	
-------	------------------	--

ARM-CRANE YES - **NO**

BLADE	YES • NO
-------	-----------------

OFFSET	YES • NO
--------	-----------------

OFFSET Cylinder	FAIR	▪ Attn	
-----------------	------	--------	--

Piping	☒ YES • NO	Breaker only	☐ • ☒ Multi
--------	---	--------------	--

COMMENT

[illegible]

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。