

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

|                 |                                        |      |      |       |           |
|-----------------|----------------------------------------|------|------|-------|-----------|
| INSPECTION DATE | 2025/8/19                              | MAKE | CAT  | MODEL | 320CU     |
| SERIAL          | CAT0320CCAPA00933                      |      |      | STAMP | NOT FOUND |
| HR METER        | 8018                                   | HR   | YEAR | YR    |           |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |      | SHOE  | 600G      |

|                                  |       |                              |                                 |
|----------------------------------|-------|------------------------------|---------------------------------|
| <b>ENGINE : MODEL</b>            |       | <b>S/N</b>                   | 7JK50951                        |
| Oil leakage                      | FAIR  | Attn                         |                                 |
| Blow-By                          | FAIR  | Attn                         | A LITTLE · MIDDLE · SEVERE      |
| Sound                            | FAIR  | Attn                         |                                 |
| Oil                              | FAIR  | Attn                         |                                 |
| Exhaust Color                    | FAIR  | Attn                         |                                 |
| US EPA                           | YES   | NO                           |                                 |
| <b>MAIN PUMP</b>                 |       |                              |                                 |
| Sound                            | FAIR  | Attn                         |                                 |
| Oil leakage                      | FAIR  | Attn                         |                                 |
| Power                            | FAIR  | Attn                         |                                 |
| <b>COOLING SYSTEM</b>            |       |                              |                                 |
| Radiator                         | FAIR  | Attn                         |                                 |
| Oil Cooler                       | FAIR  | Attn                         |                                 |
| <b>OPERATING SYSTEM</b>          |       |                              |                                 |
| Swing                            | FAIR  | Attn                         |                                 |
| Travel                           | FAIR  | Attn                         | *1                              |
| <b>INTERIOR See Photos. 写真参照</b> |       |                              |                                 |
| INTERIOR COND.                   | CLEAN | FAIR                         | DIRTY                           |
| Operator's Seat                  | FAIR  | Attn                         |                                 |
| Glasses                          | FAIR  | Attn                         |                                 |
| AirCon                           | A/C   | H/C · H only · C only · None |                                 |
| <b>BOOM / ARM / BKT</b>          |       |                              |                                 |
| Boom                             | FAIR  | Attn                         |                                 |
| Boom Cylinder                    | FAIR  | Attn                         | 左シリンダーサビあり LEFT CYLINDER: RUSTY |
| Arm                              | FAIR  | Attn                         | ショートアーム SHORT ARM               |
| Arm Cylinder                     | FAIR  | Attn                         |                                 |
| ATTACHMENT                       | FAIR  | Attn                         |                                 |
| BKT Cylinder                     | FAIR  | Attn                         |                                 |

|                                                                      |                                             |
|----------------------------------------------------------------------|---------------------------------------------|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |                                             |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 3                                           |
| <b>COMMENT</b>                                                       |                                             |
| シューリンク固着大 TRACK LINKS: MUCH STUCK                                    |                                             |
| 左足走行モーターより油漏れ小 LEFT TRAVEL MOTOR: OIL LEAKING                        |                                             |
| シューフレーム左前補修あり                                                        |                                             |
| FRONT PART OF LEFT TRACK FRAME: REPAIRED                             |                                             |
| BKT                                                                  | STD / SLOPE / NARROW / SKELETON / OTHER ( ) |
| Lever                                                                | LONG · WRIST                                |
| Multi                                                                | MULTI · 2 · NO                              |
| ARM-CRANE                                                            | YES · NO                                    |
| BLADE                                                                | YES · NO                                    |
| OFFSET                                                               | YES · NO                                    |
| OFFSET Cylinder                                                      | FAIR · Attn                                 |
| Piping                                                               | YES · NO Breaker only · Multi               |
| <b>COMMENT</b>                                                       |                                             |
| トンネル仕様 FOR TUNNEL USE                                                |                                             |
| モニター不良あり MONITOR: MALFUNCTION                                        |                                             |
| A/C不良あり A/C: MALFUNCTION                                             |                                             |
| 走行レバーより室内にオイル上がりあり                                                   |                                             |
| LOWER PART OF TRAVEL LEVERS: OIL LEAKING                             |                                             |
| CAB下より油漏れあり BOTTOM OF CAB: OIL LEAKING                               |                                             |
| アタッチメントなし WITHOUT ATTACHMENT                                         |                                             |
| *1 リンク固着のため走行困難                                                      |                                             |
| *1 HARD TO TRAVEL (TRACK LINKS: MUCH STUCK)                          |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
|                                                                      |                                             |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |                                             |
| 2                                                                    |                                             |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。