

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2025/8/19	MAKE	KAWASAKI	MODEL	KVR4T		
SERIAL	KVR4-0232			STAMP	KVR4-0232		
HR METER	1517	HR	Odometer	–	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	7.50-16		

ENGINE : MODEL		S/N	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
OPERATION PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	PS · DD		
Transmission	FAIR · Attn		
Travel	FAIR · Attn		
FOOT BRAKE	FAIR · Attn		
PARKING BRAKE	FAIR · Attn	*1	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
OTHERS			
Vibratory	FAIR · Attn		
Watering	FAIR · Attn	*2	
Articulate	FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
*1 効き甘い、引いた状態でバック走行のみ可 (ブレーキONの状態でもバック走行はできてしまう)	
*1 BRAKE: LOOSE, ONLY ABLE TO TRAVEL BACKWARD EVEN PUTTING THE PARKING BRAKE ON	
*2 R散水ホース切れ、Fノズル2ヶ所目詰まり、フィルター水漏れあり	
*2 REAR WATERING HOSE: HUGE CUT, 2 FRONT WATERING NOZZLES: CLOGGED, WATER FILTER: WATER LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。