

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/8/26	MAKE	TADANO	MODEL	GR-250N-1
SERIAL No.	PLATE : FB4894		STAMP : TR256-1609		
HR METER	6836	HR	Odometer	67739	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	オイル混入あり OIL: MIXED
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · NG	
Swing	FAIR · Attn	
Travel	FAIR · Attn	
TRANSMISSION		
Transmission	FAIR · Attn	
No. OF GEARS	4	GEARS
4WD	4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	切れ大 HUGE CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
COMMENT		

BOOM					
No. of Section	4 SECTIONS				
CRACK/ENFORCEMENT	(FAIR) ▪ Attn				
DERRICKING CYL.	(FAIR) ▪ Attn				
EXTENSION CYL.	(FAIR) ▪ Attn				
JIB	(YES) ▪ NO				
JIB TYPE	STD ▪ (PWR)				
MAIN & SUB WIRE	(YES) ▪ NO				
FREE FALL	(YES) ▪ NO				
HOOKE	25t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR				
COMMENT 					
OUTRIGGERS					
OUTRIGGERS	X ▪ (H)				
OUTRIGGERS COND.	(FAIR) ▪ Attn				
Oil leakage (JACK CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
COMMENT 					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。