

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

|                 |                |      |                    |        |           |
|-----------------|----------------|------|--------------------|--------|-----------|
| INSPECTION DATE | 2025/8/26      | MAKE | TADANO             | MODEL  | GR-120N-1 |
| SERIAL No.      | PLATE : FD0815 |      | STAMP : TR120-0815 |        |           |
| HR METER        | 13157          | HR   | Odometer           | 112691 | km        |
| TIRE SIZE       | 275/80R22.5    |      | YEAR               | 2005   | YR        |

| ENGINE : MODEL |                        | S/N                            |
|----------------|------------------------|--------------------------------|
| Oil leakage    | FAIR <span>Attn</span> | E/G下部にじみあり BOTTOM: OIL OOOZING |
| Blow-By        | FAIR <span>Attn</span> | A LITTLE ・ MIDDLE ・ SEVERE     |
| Sound          | FAIR <span>Attn</span> |                                |
| Oil            | FAIR <span>Attn</span> |                                |
| Exhaust Color  | FAIR <span>Attn</span> |                                |

## OPERATION PUMP

|             |      |      |  |
|-------------|------|------|--|
| Sound       | FAIR | Attn |  |
| Oil leakage | FAIR | Attn |  |
| Power       | FAIR | Attn |  |

## COOLING SYSTEM

|            |      |      |  |
|------------|------|------|--|
| Radiator   | FAIR | Attn |  |
| Oil Cooler | FAIR | Attn |  |

## OPERATING SYSTEM

|          |      |      |  |
|----------|------|------|--|
| Computer | OK   | NG   |  |
| Swing    | FAIR | Attn |  |
| Travel   | FAIR | Attn |  |

## TRANSMISSION

|              |             |       |
|--------------|-------------|-------|
| Transmission | FAIR • Attn |       |
| No. OF GEARS | 4           | GEARS |
| 4WD          | 4WD • 6WD   |       |

**INTERIOR** See Photos. 写真参照

|                 |                                    |           |
|-----------------|------------------------------------|-----------|
| INTERIOR COND.  | CLEAN • FAIR • DIRTY               |           |
| Operator's Seat | FAIR • Attn                        | 穴あり HOLES |
| Glasses         | FAIR • Attn                        |           |
| AirCon          | A/C • H/C • H only • C only • None |           |

## COMMENT

|  |  |
|--|--|
|  |  |
|  |  |
|  |  |
|  |  |

**BOOM**

| No. of Section    | 6         | SECTIONS |  |
|-------------------|-----------|----------|--|
| CRACK/ENFORCEMENT | FAIR      | ▪ Attn   |  |
| DERRICKING CYL.   | FAIR      | ▪ Attn   |  |
| EXTENSION CYL.    | FAIR      | ▪ Attn   |  |
| JIB               | YES       | ▪ NO     |  |
| JIB TYPE          | STD       | ▪ PWR    |  |
| MAIN & SUB WIRE   | YES       | ▪ NO     |  |
| FREE FALL         | YES       | ▪ NO     |  |
| HOOK              | 12t, BALL |          |  |

**UNDERCARRIAGE :** See Photos. 写真参照

|                                                              |                           |   |
|--------------------------------------------------------------|---------------------------|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED) |                           | 4 |
| TIRE WEAR                                                    | FAIR • WORN • UNEVEN WEAR |   |

## COMMENT

|  |
|--|
|  |
|  |

## OUTRIGGERS

|                          |                    |       |      |       |
|--------------------------|--------------------|-------|------|-------|
| OUTRIGGERS               | X • <b>H</b>       |       |      |       |
| OUTRIGGERS COND.         | <b>FAIR</b> • Attn |       |      |       |
| Oil leakage (JACK CYL.)  | FRONT              | L • R | REAR | L • R |
| Oil leakage (SLIDE CYL.) | FRONT              | L • R | REAR | L • R |

## COMMENT

[illegible]

|                                                                             |          |
|-----------------------------------------------------------------------------|----------|
| <b>RUST of BODY</b> (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | <b>4</b> |
|-----------------------------------------------------------------------------|----------|

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。