

INSPECTION SHEET 検品書
WHEEL EXCAVATOR タイヤバックホー

INSPECTION DATE	2025/8/8	MAKE	KOMATSU	MODEL	PW128UU-1S
SERIAL	1285	STAMP	PW1281-1285		
HR METER	4674	HR	Odometer	3230 + 6344	km
CAB/CNP	ROPS CAB / CAB / ROPS	CNP / CNP / NONE	TIRE SIZE	9.00-20	YEAR

ENGINE : MODEL	4D102E-1	S/N	26276642
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN ・ FAIR ・		DIRTY
Operator's Seat	FAIR ・ Attn	破れあり CUTS	
Glasses	FAIR ・ Attn		
AirCon	A/C ・ H/C ・ H only ・ C only ・ None		

BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	*1
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE :	See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR · WORN · UNEVEN WEAR

COMMENT	右ステアリングシリンダー油漏れ小 RIGHT STEERING CYLINDER: OIL LEAKING 左右Fダンパーシリンダーにじみあり FRONT DUMPER CYLINDERS: OIL OOZING
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
OUTRIGGERS COND.	FAIR · Attn

COMMENT	リアシート上に部材一式、カバーシートあり SOME PARTS & TARP: PUTTING ON REAR SEAT ブーム横配管にじみあり SOME PIPES AT BOOM: OIL OOZING ワンタッチ付 W/ONE-TOUCH CAB内にカバー、チェーンあり COVER & TIRE CHAINS: PUTTING IN CAB 付属品: タイヤ2本、回転式カッター、ブレーカー、フォークグラブ 2 PIECES OF TIRES, ROTATABLE CUTTER, BREAKER (OKADA TOP100-1255), & FORK GRAB (IIDA HS400L-10619) AS SAPRE *1 左右シリンダー、展張シリンダーにじみあり *1 CYLINDERS & TENSIONING CYLINDER: OIL OOZING
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。