

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/5/26	MAKE	TADANO	MODEL	GR-600N-1
SERIAL No.	PLATE : FD5102		STAMP : TR600-0102		
HR METER	1266	HR	Odometer	58178	km
TIRE SIZE	505/95R25		YEAR	2004	YR

ENGINE : MODEL		S/N
Oil leakage	FAIR Attn	E/Gヘッドにじみあり CYLINDER HEAD: OIL OOZING
Blow-By	FAIR Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR Attn	
Oil	FAIR Attn	
Exhaust Color	FAIR Attn	

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR - Attn	
Oil Cooler	FAIR - Attn	

OPERATING SYSTEM		
Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn

TRANSMISSION		
Transmission	FAIR • Attn	
No. OF GEARS	4	GEARS
4WD	4WD • 6WD	

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN ・ FAIR ・ DIRTY	
Operator's Seat	FAIR ・ Attn	切れあり CUTS
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・ None	

COMMENT

.....

.....

.....

BOOM		
No. of Section	6	SECTIONS
CRACK/ENFORCEMENT	FAIR	▪ Attn
DERRICKING CYL.	FAIR	▪ Attn
EXTENSION CYL.	FAIR	▪ Attn にじみあり OIL OOZING
JIB	YES	▪ NO
JIB TYPE	STD	▪ PWR
MAIN & SUB WIRE	YES	▪ NO
FREE FALL	YES	▪ NO
HOOK	60t, 25t, BALL	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	4
TIRE WEAR	FAIR • WORN • UNEVEN WEAR

COMMENT	

OUTRIGGERS				
OUTRIGGERS	X	•	(H)	
OUTRIGGERS COND.	(FAIR)	•	Attn	
Oil leakage (JACK CYL.)	FRONT	(L)	• (R)	REAR (L) • (R)
Oil leakage (SLIDE CYL.)	FRONT	L	• R	REAR L • R

COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。