

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/9/1	MAKE	CAT	MODEL	313DCR
SERIAL	CAT0313DCLCE00368		STAMP	CAT0313DCLCE00368	
HR METER	11738 / 11740 HR		YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE :		MODEL	C4.2	S/N
Oil leakage	☒ FAIR	Attn		
Blow-By	☒ FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE	
Sound	☒ FAIR	Attn		
Oil	☒ FAIR	Attn		
Exhaust Color	☒ FAIR	Attn		
US EPA	☒ YES	NO		
MAIN PUMP				
Sound	☒ FAIR	Attn		
Oil leakage	☒ FAIR	Attn		
Power	☒ FAIR	Attn		
COOLING SYSTEM				
Radiator	☒ FAIR	Attn		
Oil Cooler	☒ FAIR	Attn		
OPERATING SYSTEM				
Swing	☒ FAIR	Attn		
Travel	☒ FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	☒ FAIR	DIRTY	
Operator's Seat	FAIR	☒ Attn	破れあり HUGE CUTS	
Glasses	☒ FAIR	Attn		
AirCon	☒ A/C	H/C	H only	C only ・ None
BOOM / ARM / BKT				
Boom	☒ FAIR	Attn		
Boom Cylinder	FAIR	☒ Attn	にじみあり OIL OOZING	
Arm	☒ FAIR	Attn		
Arm Cylinder	☒ FAIR	Attn		
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	☒ Attn	にじみあり OIL OOZING	

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
右キャリアローラー傾いている RIGHT CARRIER ROLLER: BENT			
シューパッド1枚飛ばしで付いている			
RUBBER PADS: ATTACHED IN EVERY OTHER SHOE PLATE			
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()		
Lever	LONG	☒ WRIST	
Multi	MULTI	2	☒ NO
ARM-CRANE	YES	☒ NO	
BLADE	☒ YES	NO	
OFFSET	YES	☒ NO	
OFFSET Cylinder	FAIR	Attn	
Piping	☒ YES	NO	Breaker only ・ Multi 5
COMMENT			
E/Gフードに行くまでの手すりの片方が外れている			
LOWER SIDE OF HANDRAIL AT RIGHT PART OF BODY: NOT ATTACHED			
運転席ドア開閉しづらい DOOR: HARD TO OPEN & CLOSE			
アタッチメントなし WITHOUT ATTACHMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。