

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |        |       |         |
|-----------------|----------------------------------------|------|--------|-------|---------|
| INSPECTION DATE | 2025/8/19                              | MAKE | KUBOTA | MODEL | U-20-3S |
| SERIAL          | 15343                                  |      | STAMP  | 15343 |         |
| HR METER        | 2818                                   |      | HR     | YEAR  | YR      |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE   | 250R  |         |

|                           |       |       |                            |         |
|---------------------------|-------|-------|----------------------------|---------|
| ENGINE : MODEL            |       | D1105 | S/N                        | 1DM2299 |
| Oil leakage               | FAIR  | Attn  |                            |         |
| Blow-By                   | FAIR  | Attn  | A LITTLE · MIDDLE · SEVERE |         |
| Sound                     | FAIR  | Attn  |                            |         |
| Oil                       | FAIR  | Attn  |                            |         |
| Exhaust Color             | FAIR  | Attn  |                            |         |
| US EPA                    | YES   | NO    |                            |         |
| MAIN PUMP                 |       |       |                            |         |
| Sound                     | FAIR  | Attn  |                            |         |
| Oil leakage               | FAIR  | Attn  |                            |         |
| Power                     | FAIR  | Attn  |                            |         |
| COOLING SYSTEM            |       |       |                            |         |
| Radiator                  | FAIR  | Attn  |                            |         |
| Oil Cooler                | FAIR  | Attn  |                            |         |
| OPERATING SYSTEM          |       |       |                            |         |
| Swing                     | FAIR  | Attn  | ガタあり SWING: LOOSE          |         |
| Travel                    | FAIR  | Attn  |                            |         |
| INTERIOR See Photos. 写真参照 |       |       |                            |         |
| INTERIOR COND.            | CLEAN | FAIR  | DIRTY                      |         |
| Operator's Seat           | FAIR  | Attn  | 破れあり CUTS                  |         |
| Glasses                   | FAIR  | Attn  |                            |         |
| AirCon                    | A/C   | H/C   | H only                     | C only  |
|                           |       |       |                            | None    |
| BOOM / ARM / BKT          |       |       |                            |         |
| Boom                      | FAIR  | Attn  |                            |         |
| Boom Cylinder             | FAIR  | Attn  |                            |         |
| Arm                       | FAIR  | Attn  |                            |         |
| Arm Cylinder              | FAIR  | Attn  |                            |         |
| ATTACHMENT                | FAIR  | Attn  |                            |         |
| BKT Cylinder              | FAIR  | Attn  |                            |         |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。