

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/8/6	MAKE	CAT	MODEL	966M
SERIAL	CAT0966MELMM10310			STAMP	CAT0966MELMM10310
HR METER	19089	HR	Odometer	79280	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	26.5R25
YEAR	2018	YR			

ENGINE : MODEL		C9.3	S/N	SYE21892
Oil leakage	☒ FAIR	Attn		
Blow-By	☒ FAIR	Attn A LITTLE • MIDDLE • SEVERE		
Sound	☒ FAIR	Attn		
Oil	☒ FAIR	Attn		
Exhaust Color	☒ FAIR	Attn		
US EPA	☒ YES	☐ NO		
OPERATION PUMP				
Sound	☒ FAIR	Attn		
Oil leakage	☒ FAIR	Attn		
Power	☒ FAIR	Attn		
COOLING SYSTEM				
Radiator	☒ FAIR	Attn		
Oil Cooler	☒ FAIR	Attn		
TRANSMISSION & TRAVEL				
T/M TYPE	☒ PS	☐ DD		
Transmission	☒ FAIR	Attn		
Travel	☒ FAIR	Attn		
FOOT BRAKE	☒ FAIR	Attn		
PARKING BRAKE	☒ FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN • ☒ FAIR •	DIRTY		
Operator's Seat	☒ FAIR	Attn		
Glasses	☒ FAIR • ☒ Attn	*1		
AirCon	☒ A/C •	☐ H/C • ☐ H only • ☐ C only • ☐ None		
FRONT & CYLINDERS				
Arm	☒ FAIR	Attn		
Bell crank	☒ FAIR	Attn		
Bucket	☒ FAIR	Attn		
Articulate	☒ FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	☒ FAIR • ☐ WORN • ☐ UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☒ LEVER STEERING	
RIDE CONTROL	☒ YES • ☐ NO
ATTACHMENTS	
STD BKT	☒ YES • ☐ OTHER
BLADE	☒ YES • ☒ NO Piping for Tilt ☐ YES • ☒ NO
COMMENT	
ステアリングレバー下がったまま固着あり(ロック解除した状態で固着)	
STEERING LEVER LOCK: STUCK AT RELEASED POSITION	
(UNABLE TO LOCK)	
*1 F左側下部ひび割れあり	
*1 LOWER LEFT PART OF WINDSHIELD: CRACKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。