

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/20	MAKE	CAT	MODEL	308DCR
SERIAL	CAT0308DTHSA01017			STAMP	CAT0308DTHSA01017
HR METER	3951 / 3950		HR	YEAR	2011 YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	450G PADS

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタ大 SWING: MUCH LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	2ピースブーム 2-PIECE BOOM
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	*1
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE :						See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								3			
COMMENT 											
BKT	STD / SLOPE / NARROW / SKELETON / OTHER)										
Lever	LONG ▪ WRIST										
Multi	MULTI ▪ 2 ▪ NO										
ARM-CRANE	YES ▪ NO										
BLADE	YES ▪ NO										
OFFSET	YES ▪ NO										
OFFSET Cylinder	FAIR ▪ Attn										
Piping	YES ▪ NO		Breaker only ▪ Multi							5	
COMMENT アタッチメント:回転式フォークグラブ ATTACHMENT: ROTATABLE FORK GRAB SG-25R-16937 *1 ホース周り、シリンダー油漏れ、ガタあり *1 AROUND HOSES & CYLINDER: OIL LEAKING, LOOSE 											
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)										3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。